# Bruhath Bangalore Mahanagara palike,

## Inspection Report

| | | |
|---|---|---|
| 1 | Name of work | Maintenance of toilet at J.P.Park in Ward NO.17 in RRN Zone |
| 2 | Administration Approval & Date | CE/RRN/AS/11/10-11 Dtd 23-04-2011 by CE (RRN) |
| 3 | Technical Sanction Estimate No. & Date | CE/RRNZ/TS/21/10-11 dtd:23-04-2011 by CE (RRN) |
| 4 | Estimate Amount | Rs.20.00/- Lakhs |
| 5 | Job Code No. | 017-11-000042 |
| 6 | P-Code | P-0974 |
| 7 | Agreement No & date | EE(P)/RRN/AG No./18/2011-12 Dtd.04-05-2011 |
| 8 | Work order Number & Date | EE/Proj/RRN/W.O/18/2011-12 Dtd.04-05-2011 |
| 9 | Contract Amount as per Agreement | Estimated Amount +10% |
| 10 | Bill Amount | Rs.19,06,163/- |
| 11 | B.R. No. & Date | 328/2012-13 dt.30-08-2013 |
| 12 | Agency | KRIDL |
| 13 | M.B. Number & Page No. of Measurement recordes | 516/ Pages 51519 to 51536 |
| 14 | Date of Inspection | 5/7/2015 |
| 15 | Enclusures | 1) Extract of MB No.516 Page No.51536<br>2) 4 Number of photos taken during inspection |
| 16 | Inspection Report | The above site was Inspected by along with the concerned officials. The measurements were checked by me and found to satisfactory |

5/7/2015

EE (P) RR Nagara

(R.Sathyanarayana)
Inspection Report officer,

Rough

# M.A.R. 57 (Rule 116)

Measurement Book

No. C/09

No.....

From.....To.....051536

of work.....

of Contractor of nature of Agency.....

of commencement of work.....

| Full description, etc, of work | Dimensions | | | | Contents | Reference to last Measurement | Reference to last Measurement |
|---|---|---|---|---|---|---|---|
| | Number | Length | Breadth | Depth | | | |
| | 3 | 4 | 5 | 6 | 7 | 8 | 8 |
| Main Gate 2 Statue | | | | | | | |




t:- 50.00 lacs

7

Nagar Zone

1...st:-

Sanitary and above ...resly in clear fom ...plik as

80.00

N.T.S with tal Coope ...l machine ...cted, in. machinery

5/7/2018

Inspection Officer